

## **NOTICE TO MARINERS**

NO 35 of 2018

## Notification of Swansea Bay Outfall Beacon replaced by Temporary Buoy

Mariners are advised that with immediate effect the following missing beacon has been replaced with a temporary buoy. Characteristic: Red Can, Unlighted, No Topmark.

**Swansea Bay Outfall Beacon** 

Latitude 51 36.245 N Longitude 003 56.786 W

For and on behalf of Welsh Water.

HARBOUR MASTER, SOUTH WALES

Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

06<sup>th</sup> December 2018.

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.