



Associated British Ports South Wales

NOTICE TO MARINERS

NO 5 of 2018

Notification of Newport No 2 Buoy topmark is loose and obscuring the light

Mariners are advised that with immediate effect the following buoy is reported as having its Top Mark loose and obscuring the light.

Newport No 2 Buoy

**Latitude 51 31'52 N
Longitude 002 58'30 W**

**HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY**

01st February 2018

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.