



Associated British Ports South Wales

NOTICE TO MARINERS

NO 20 OF 2012

NOTIFICATION OF PORT TALBOT BUOYS 3 AND 4 BEING OUT OF POSITION

Mariners are advised that with immediate effect the following buoys are reported as being Out of Position: -

PT3 – South Outer: -

Latitude 51° 033' 707" N

Longitude 003° 51.292" W

PT4 – North Outer: -

Latitude 51° 033' 787" N

Longitude 003° 51.372" W

The effect of the Buoys being out of position is that the Channel now narrows to 100m.

Mariners are to proceed with Caution

Position will be Checked/Rectified as soon as possible.

MARINE MANAGER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

17th August 2012

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk