



# Associated British Ports

## South Wales

### NOTICE TO MARINERS

NO 14 OF 2014

### NOTIFICATION OF PT-5 SOUTH INNER BUOY REPORTED AS BEING NOT IN CORRECT CHARTED POSITION

Mariners are advised that the PT-5 South Inner Buoy is reported as being approximately 80m South of its Charted Position:

### PT-5 South Inner Buoy

Latitude	51° 34.094"	N
Longitude	003° 50.155"	W

HARBOUR MASTER, SOUTH WALES  
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

19<sup>th</sup> June 2014

All ABP South Wales Notices to Mariners may be viewed on: - [www.southwalesports.co.uk](http://www.southwalesports.co.uk)