



Associated British Ports South Wales

NOTICE TO MARINERS

NO 22 OF 2015

THE WEST USK LIGHTED BUOY IS REPORTED AS HAVING A MISSING TOPMARK

Mariners are advised that the following buoy is reported as having a Missing Topmark.

West Usk Lighted Buoy: -

**Latitude 51° 31.673" N
Longitude 002° 58.502" W**

**HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY**

14th May 2015

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.