



Associated British Ports South Wales

NOTICE TO MARINERS

NO 23 OF 2016

NOTIFICATION OF SOUTH CARDIFF LIGHTED BUOY MISSING ITS TOP MARK

Mariners are advised that with immediate effect the following buoy is reported as having its Top Mark Missing: -

SOUTH CARDIFF Lighted Buoy: -

**Latitude 51° 24.183' N
Longitude 003° 08.568' W**

**HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY**

19th August 2016

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.