

# **Associated British Ports South Wales**

## **NOTICE TO MARINERS.**

**NO 52 of 2025**

### **South Outer Fairway Buoy Unlit and Missing Topmark, Port Talbot Harbour**

Mariners are advised the following floating navigational aid has been reported as being unlit and missing its Topmark.

South Outer Fairway Buoy – Port Talbot Harbour

Lat – 51 33.707N  
Long – 003 51.292W

**HARBOUR MASTER SOUTH WALES**  
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

Date 19/10/2025.

South Wales Notices to Mariners may be viewed on: - [www.southwalesports.co.uk](http://www.southwalesports.co.uk)

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.