

Associated British Ports South Wales

NOTICE TO MARINERS.

Notice of Cancellation NO 52 of 2025

The below has now been repaired and is fully functioning.

South Outer Fairway Buoy Unlit and Missing Topmark, Port Talbot Harbour

Mariners are advised the following floating navigational aid has been reported as being unlit and missing its Topmark.

South Outer Fairway Buoy – Port Talbot Harbour

Lat – 51 33.707N
Long – 003 51.292W

HARBOUR MASTER SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

Date 19/10/2025.

South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.