

NOTICE TO MARINERS

NO 10 OF 2013

EAST USK OCCULTING SECTOR LIGHT ADJUSTMENT AND MOVEMENT OF BUOYS

Mariners are advised that the East Usk sector light has been adjusted 5 degrees to the East: -

Sectors as follows: -

 Occ Green
 013-017 deg

 Occ White
 017-019 deg

 Occ Red
 019-023 deg

The following buoys have been moved approximately 40m to the SE and are now in the following positions: -

No1	332774 180986	51 31 25.575 N	02 58 13.377 W
No2	332469 181805	51 31 51.951 N	02 58 29.767 W
No3	332423 182260	51 32 06.658 N	02 58 32.469 W

HARBOUR MASTER, SOUTH WALES

Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY 8th April 2013

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.