

## **NOTICE TO MARINERS**

## NO 12 OF 2013

## NOTIFICATION OF INNER WRACH BUOY BEING REPORTED AS OUT OF POSITION

Mariners are advised that with immediate effect the following buoy is reported as being out of position until further notice: -

C-7 Inner Wrach Buoy

 Latitude
 51° 26.72"
 N

 Longitude
 003° 09.56"
 W

THE BUOY IS APPROXIMATELY **50m** TO THE SOUTH OF IT'S CHARTED POSITION

HARBOUR MASTER, SOUTH WALES Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

26<sup>th</sup> April 2013

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.