



Associated British Ports South Wales

NOTICE TO MARINERS

NO 19 OF 2013

NOTIFICATION OF INNER WRACH BUOY BEING RESTORED TO CHARTED POSITION AND LIGHT CHARACTERISTICS

Mariners are advised that with immediate effect the following buoy is reported as having been restored to charted position and light characteristics.

C-7 Inner Wrach Buoy

Latitude	51° 26.72"	N
Longitude	003° 09.56"	W

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

28th May 2013

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.