



Associated British Ports South Wales

NOTICE TO MARINERS

NO 20 OF 2013

NOTIFICATION OF INNER WRACH BUOY BEING REPORTED AS OUT OF POSITION

Mariners are advised that with immediate effect the following buoy is reported as being out of position until further notice: -

C-7 Inner Wrach Buoy

Latitude 51° 26.72" N
Longitude 003° 09.56" W

**THE BUOY IS REPORTED AS BEING APPROXIMATELY
60 METRES EAST OF ITS CHARTED POSITION**

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

30th May 2013

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk