



# Associated British Ports

## South Wales

### NOTICE TO MARINERS

NO 3 OF 2013

### NOTIFICATION OF INNER WRACH BUOY BEING RESTORED TO CORRECT POSITION

Mariners are advised that with immediate effect the following buoy is reported as being restored to correct position -

#### **C-7 Inner Wrach Buoy**

<b>Latitude</b>	<b>51° 26.72"</b>	<b>N</b>
<b>Longitude</b>	<b>003° 09.56"</b>	<b>W</b>

**HARBOUR MASTER, SOUTH WALES**  
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

4th February 2012

All ABP South Wales Notices to Mariners may be viewed on: - [www.southwalesports.co.uk](http://www.southwalesports.co.uk)

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.