



Associated British Ports

South Wales

NOTICE TO MARINERS

NO 39 OF 2013

NOTIFICATION OF CABENDA BUOY RACON BEING RESTORED

Mariners are advised that the Cabenda Buoy Racon has been restored to correct characteristics:

South Cardinal Cabenda Buoy

Latitude	51° 33.357''	N
Longitude	003° 52.242''	W

This Notice supersedes No 29 of 2012 issued 19th November 2012

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

9th December 2013

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.