



Associated British Ports

South Wales

NOTICE TO MARINERS

NO 33 OF 2014

NOTIFICATION OF SWANSEA INNER FAIRWAY BUOY BEING REPORTED AS DAMAGED AND UNLIT

Mariners are advised that with immediate effect the following buoy is reported as being damaged with topmark missing and light extinguished: -

S-7 – Swansea Inner Fairway

Latitude 51° 36.227” N
Longitude 003° 55.672” W

HARBOUR MASTER SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

9th October 2014

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.