



# Associated British Ports South Wales

## NOTICE TO MARINERS

NO 36 OF 2014

### NOTIFICATION OF PORT TALBOT SOUTH INNER BUOY BEING REPORTED AS EXTINGUISHED

Mariners are advised that with immediate effect the following buoy is reported as being  
Extinguished: -

#### **PT 5 – Port Talbot South Inner**

**Latitude      51° 34.094” N**  
**Longitude     003° 50.155” W**

**HARBOUR MASTER SOUTH WALES**  
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

**24th November 2014**

**All ABP South Wales Notices to Mariners may be viewed on: - [www.southwalesports.co.uk](http://www.southwalesports.co.uk)**

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.