



Associated British Ports South Wales

NOTICE TO MARINERS

NO 10 OF 2016

NOTIFICATION OF WEST USK LIGHTED BUOY MISSING ITS TOP MARK

Mariners are advised that with immediate effect the following buoy is reported as having its Top Mark Missing: -

West Usk Lighted Buoy: -

**Latitude 51° 31.673" N
Longitude 002° 58.502" W**

**HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY**

15th April 2016

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.