



Associated British Ports South Wales

NOTICE TO MARINERS

NO 45 OF 2016

CANCELLATION OF N2M 40 OF 2016

THE LEADING LIGHTS ON LIBERTY STEEL BERTH HAS BEEN REPORTED AS RESTORED TO NORMAL SERVICE

Mariners are advised that the Julians Pill leading lights on Liberty Steel, in the River Usk, are reported as Restored to Normal Service

Position:

Latitude 51°33.32' N
Longitude 002°57.90' W

HARBOUR MASTER, SOUTH WALES
Queen Alexandra House, Cargo Road, CARDIFF, CF10 4LY

15th December 2016

All ABP South Wales Notices to Mariners may be viewed on: - www.southwalesports.co.uk

Owners, Agents and Charters should ensure that the contents of this notice are made known to the masters or persons in charge of their vessel or craft.